

Parts List

A Base

1 piece




220 with 45C or 55C control, armless or with fixed or 8D adjustable arms.

1 - Insert gaslift and casters into base

Push the five casters (**B**) into the holes at the end of the legs of the base (**A**). Push the wide end of the gaslift (**C**) into the center hole of the base (**A**).

3 - Secure control to seat Secure the chair control (**G**) to the seat (**D**) with 4 M6x25mm bolts (**H**).



5 - Insert gas lift into control


Position the upper half of the chair over the base and insert the gaslift (**C**) into the hole on the control (**G**).

6 - Sit in the chair


Sit in the chair to ensure the connection between the gaslift and control is secure.


2 - Secure arms to seat

Attach the arms (**E**) to the seat (**D**) with 6 M6x40mm bolts (**F**).



4 - Secure back to control Secure the back (I) to the control (G) with 3 M8x20mm bolts (J).







(for M6 bolts) 13mm wrench (for M8 bolts)

GSA

Н

Schedule