

# Care Guidelines

## Onda



### **standard upholstery:**

Vacuum up any excess dirt/spillage with close attention to the seams, area where the seat meets the back and area where the arms meet the seat/back. After, take a lint-free cloth and dip it into any water-based cleaning agent. Scrub gently over the stained area. Repeat if needed. For best results, follow the mill guidelines for your exact textile.

### **mesh:**

Mix mild soap and warm water together and using a lint-free cloth, damp it a little bit into the mixture. Dab gently where the stain is located. Use a different, dry, lint-free cloth to dry the area. Repeat if needed.

### **copper striped mesh:**

To prevent overall soil, frequently vacuum and lightly brush the best to remove dust and grime buildup. Spot clean with mild soap and water. Infrequent use of a 1:100 bleach to water solution can be used for disinfection of the mesh. The accumulate wet contact time should be limited to a maximum of two hours over the life of the chair. Regular bleach cleaning of this mesh is not recommended.

### **to best maintain your casters:**

To get the most out of your casters, it is always good to keep them as clean as possible. Once a month, gently flip your chair over and carefully use tweezers to remove all dirt/hair/debris out of the creases of the caster. Use a lint-free cloth with your preferred cleaning agent and clean the caster thoroughly. Thoroughly dry the caster with another lint-free cloth after.